

Inspection Details



Total Score : **1900/2100 (90%)**

Property Name : **60 - Artisan**

Reference Number : **INS-3382**

Last Inspected Time : **1/21/2025 01:29 PM**

Address : **2060 Zocolo St, Oxnard - 93030, California, United States**

#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
1	General Site Maintenance - Amenities	Completed	UNNACC EPTABLE	50/100(50%)	Check all amenities . (Benches , bbqs, kiosks). Clean as necessary. Report deficiencies to District representative.	Jose Sanchez	1/21/2025 12:51 PM	NA

Notes: Missing light pole, also arches need to be sanded and repainted.

After Image:

#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
---	-----------	--------	----------	----------	------------------	--------------	----------------	-------



#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
---	-----------	--------	----------	----------	------------------	--------------	----------------	-------



#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
2	General Site Maintenance - Graffiti	Completed	UNNACC EPTABLE	50/100(50%)	Remove all graffiti as necessary. Report to District representative if out of scope.	Jose Sanchez	1/21/2025 12:51 PM	NA

Notes: Please have contractor remove all stickers.

After Image:

#	Task Name	Status	Respon se	Score(%)	Task Descripti on	Inspecte d By	Inspecte d Date	Price
---	-----------	--------	--------------	----------	----------------------	------------------	--------------------	-------



#	Task Name	Status	Respon se	Score(%)	Task Descripti on	Inspecte d By	Inspecte d Date	Price
3	Planters - Weed control	Complete d	UNNACC EPTABL E	50/100(50 %)	Remove and control all weeds in planter areas.	Jose Sanchez	1/21/2025 12:44 PM	NA

Notes: Please have contractor remove all weeds from the planters beds.

After Image:

#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
---	-----------	--------	----------	----------	------------------	--------------	----------------	-------



#	Task Name	Status	Respon se	Score(%)	Task Descripti on	Inspecte d By	Inspecte d Date	Price
---	-----------	--------	--------------	----------	----------------------	------------------	--------------------	-------



#	Task Name	Status	Respon se	Score(%)	Task Descripti on	Inspecte d By	Inspecte d Date	Price
4	Trees - Sidewalks /Streets	Complete d	UNNACC EPTABL E	50/100(50 %)	Inspect areas of service to ensure trees are not encroaching on right of ways.	Jose Sanchez	1/21/2025 12:42 PM	NA

Notes: Several lifted sidewalks need to be removed and replaced.

#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
---	-----------	--------	----------	----------	------------------	--------------	----------------	-------

After Image:



#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
---	-----------	--------	----------	----------	------------------	--------------	----------------	-------



#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
5	Turf - Mowing	Completed	ACCEPTABLE	100/100(100%)	Mow turf areas as scheduled.	Jose Sanchez	1/21/2025 12:34 PM	NA

Notes: There is no existent turf on this property.

#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
6	Turf - Edging	Completed	ACCEPTABLE	100/100(100%)	Edge all turf areas as scheduled.	Jose Sanchez	1/21/2025 12:35 PM	NA

Notes: There is no existing turf on this property.

#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
7	Turf - String Trim	Completed	ACCEPTABLE	100/100(100%)	String trim areas as scheduled. (Valve boxes, posts, buildings, bbq).	Jose Sanchez	1/21/2025 12:35 PM	NA

Notes: There is no existing turf on this property.

#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
8	Turf - Low Spots	Completed	ACCEPTABLE	100/100(100%)	Check all turf areas for low spots. Fill with topper as needed.	Jose Sanchez	1/21/2025 12:35 PM	NA

Notes: There is no existing turf on this property.

#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
9	Turf - Bare spots	Completed	ACCEPTABLE	100/100(100%)	Check all turf areas for bare spots. Add topper	Jose Sanchez	1/21/2025 12:35 PM	NA

#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
					and seed as necessary. Ensure we have irrigation coverage.			

Notes: There is no existing turf on this property.

#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
10	General Site Maintenance - Litter and Trash removal	Completed	ACCEPTABLE	100/100(100%)	Empty trash cans and collect litter as needed.	Jose Sanchez	1/21/2025 12:35 PM	NA

Notes: Trash and litter have been removed from the property.

After Image:

#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
---	-----------	--------	----------	----------	------------------	--------------	----------------	-------



#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
11	General Site Maintenance - Debris control	Completed	ACCEPTABLE	100/100(100%)	Remove any debris throughout parks and right of ways.	Jose Sanchez	1/21/2025 01:03 PM	NA

Notes: All debris has been removed from the property.

After Image:

#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
---	-----------	--------	----------	----------	------------------	--------------	----------------	-------



#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
12	General Site Maintenance - Blowing hardscape	Completed	ACCEPTABLE	100/100(100%)	Blow off all hardscapes as needed. (Restrooms, sports courts, playgrounds, picnic areas, walkways).	Jose Sanchez	1/21/2025 12:45 PM	NA

#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
---	-----------	--------	----------	----------	------------------	--------------	----------------	-------

Notes: Blowing has been completed.

#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
13	Planters - Shrub pruning	Completed	ACCEPTABLE	100/100(100%)	Prune all shrubs and planter areas as scheduled.	Jose Sanchez	1/21/2025 12:44 PM	NA

Notes: Shrubs have been trimmed to standard size.

After Image:



#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
---	-----------	--------	----------	----------	------------------	--------------	----------------	-------



#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
14	Planters - Plant material	Completed	ACCEPTABLE	100/100(100%)	Inspect of degrading or missing plant material. Monitor and treat for pests.	Jose Sanchez	1/21/2025 12:43 PM	NA

Notes: Plant material is in good condition.

After Image:

#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
---	-----------	--------	----------	----------	------------------	--------------	----------------	-------



#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
15	Irrigation - Scheduling	Completed	ACCEPTABLE	100/100(100%)	Monitor and adjust all irrigation. Adjust as necessary.	Jose Sanchez	1/21/2025 12:43 PM	NA

Notes: Irrigation scheduling is acceptable.

#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
16	Irrigation - Run-Off	Completed	ACCEPTABLE	100/100(100%)	Inspect areas of service for water run-off. Repair and replace irrigation when necessary.	Jose Sanchez	1/21/2025 12:43 PM	NA

Notes: There is no irrigation runoff.

#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
17	Irrigation - Coverage	Completed	ACCEPTABLE	100/100(100%)	Ensure proper sprinkler coverage throughout turf and planter areas.	Jose Sanchez	1/21/2025 12:43 PM	NA

Notes: Irrigation coverage is acceptable.

#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
18	Irrigation - Wet spots	Completed	ACCEPTABLE	100/100(100%)	Inspect areas of service for wet spots in turf and planters. Adjust and repair irrigation as needed.	Jose Sanchez	1/21/2025 12:43 PM	NA

Notes: There are no irrigation wet spots.

#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
19	Irrigation - Valve boxes	Completed	ACCEPTABLE	100/100(100%)	Inspect areas of service for broken or missing valve box lids.	Jose Sanchez	1/21/2025 12:43 PM	NA

Notes: All irrigation valve boxes are acceptable.

#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
20	Trees - Down and broken branches	Completed	ACCEPTABLE	100/100(100%)	Removed down and broken branches.	Jose Sanchez	1/21/2025 12:43 PM	NA

Notes: There are no downed or broken branches.

#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
21	Trees - Weed	Completed	ACCEPTABLE	100/100(100%)	Inspect tree wells	Jose Sanchez	1/21/2025 01:03 PM	NA

#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
	control				for weeds. Remove and treat as needed.			

Notes: There are no existing tree wells.

