

Inspection Details



Total Score : **2000/2100 (95%)**

Property Name : **54 - Meadow Crest**

Reference Number : **INS-3363**

Last Inspected Time : **1/30/2025 01:44 PM**

Address : **1062 Ambrosia St, Oxnard - 93030, California, United States**

#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
1	Irrigation - Run-Off	Completed	UNNACC EPTABLE	50/100(50%)	Inspect areas of service for water run-off. Repair and replace irrigation when necessary.	Gustavo Martinez	1/30/2025 08:58 AM	NA

Notes: Water run off, created by damaged sprinkler and possible lateral break.

After Image:

#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
---	-----------	--------	----------	----------	------------------	--------------	----------------	-------



#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
---	-----------	--------	----------	----------	------------------	--------------	----------------	-------



#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
---	-----------	--------	----------	----------	------------------	--------------	----------------	-------



#	Task Name	Status	Respon se	Score(%)	Task Descripti on	Inspecte d By	Inspecte d Date	Price
---	-----------	--------	--------------	----------	----------------------	------------------	--------------------	-------



#	Task Name	Status	Respon se	Score(%)	Task Descripti on	Inspecte d By	Inspecte d Date	Price
2	Trees - Weed control	Complete d	UNNACC EPTABL E	50/100(50 %)	Inspect tree wells for weeds. Remove and treat as needed.	Gustavo Martinez	1/30/2025 08:56 AM	NA

Notes: Weeds need attention.

After Image:

#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
---	-----------	--------	----------	----------	------------------	--------------	----------------	-------



#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
---	-----------	--------	----------	----------	------------------	--------------	----------------	-------



#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
3	Turf - Mowing	Completed	ACCEPTABLE	100/100(100%)	Mow turf areas as scheduled.	Gustavo Martinez	1/30/2025 08:41 AM	NA

Notes: Turf has been mowed correctly.

After Image:

#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
---	-----------	--------	----------	----------	------------------	--------------	----------------	-------



#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
---	-----------	--------	----------	----------	------------------	--------------	----------------	-------



#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
4	Turf - Edging	Completed	ACCEPTABLE	100/100(100%)	Edge all turf areas as scheduled.	Gustavo Martinez	1/30/2025 08:41 AM	NA

Notes: Edging has been completed.

After Image:

#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
---	-----------	--------	----------	----------	------------------	--------------	----------------	-------



#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
5	Turf - String Trim	Completed	ACCEPTABLE	100/100(100%)	String trim areas as scheduled. (Valve boxes, posts, buildings, bbq).	Gustavo Martinez	1/30/2025 08:43 AM	NA

#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
6	Turf - Low Spots	Completed	ACCEPTABLE	100/100(100%)	Check all turf areas for low spots. Fill with topper as needed.	Gustavo Martinez	1/30/2025 09:07 AM	NA

#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
7	Turf - Bare spots	Completed	ACCEPTABLE	100/100(100%)	Check all turf areas for bare spots. Add topper and seed as necessary. Ensure we have irrigation coverage.	Gustavo Martinez	1/30/2025 09:04 AM	NA

Notes: Turf bare area needs attention.

After Image:

#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
---	-----------	--------	----------	----------	------------------	--------------	----------------	-------



#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
8	General Site Maintenance - Litter and Trash removal	Completed	ACCEPTABLE	100/100(100%)	Empty trash cans and collect litter as needed.	Gustavo Martinez	1/30/2025 08:44 AM	NA

Notes: No litter to report.

#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
9	General Site Maintenance - Debris control	Completed	ACCEPTABLE	100/100(100%)	Remove any debris throughout parks and right of ways.	Gustavo Martinez	1/30/2025 08:44 AM	NA

Notes: No debris to report.

#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
10	General Site Maintenance - Amenities	Completed	ACCEPTABLE	100/100(100%)	Check all amenities (Benches, bbqs, kiosks). Clean as necessary. Report deficiencies to District representative.	Gustavo Martinez	1/30/2025 08:50 AM	NA

After Image:

#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
---	-----------	--------	----------	----------	------------------	--------------	----------------	-------



#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
11	General Site Maintenance - Graffiti	Completed	ACCEPTABLE	100/100(100%)	Remove all graffiti as necessary. Report to District representative if out of scope.	Gustavo Martinez	1/30/2025 08:44 AM	NA

Notes: No graffiti to report.

#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
12	General Site Maintenance - Blowing hardscape	Completed	ACCEPTABLE	100/100(100%)	Blow off all hardscapes as needed. (Restrooms, sports courts, playgrounds, picnic areas, walkways).	Gustavo Martinez	1/30/2025 08:44 AM	NA

Notes: Hardscape has been cleared correctly.

After Image:



#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
13	Planters - Shrub pruning	Completed	ACCEPTABLE	100/100(100%)	Prune all shrubs and planter areas as scheduled.	Gustavo Martinez	1/30/2025 08:45 AM	NA

Notes: Shrubs have been trimmed correctly.

After Image:



#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
14	Planters - Weed control	Completed	ACCEPTABLE	100/100(100%)	Remove and control all weeds in planter areas.	Gustavo Martinez	1/30/2025 08:46 AM	NA

Notes: Weeds are under control.

After Image:



#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
15	Planters - Plant material	Completed	ACCEPTABLE	100/100(100%)	Inspect of degrading or missing plant material. Monitor and treat for pests.	Gustavo Martinez	1/30/2025 08:46 AM	NA

Notes: Plant material is healthy.

After Image:



#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
---	-----------	--------	----------	----------	------------------	--------------	----------------	-------



#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
16	Irrigation - Scheduling	Completed	ACCEPTABLE	100/100(100%)	Monitor and adjust all irrigation. Adjust as necessary.	Gustavo Martinez	1/30/2025 08:47 AM	NA

Notes: Schedule is correctly, adjust as needed.

After Image:

#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
---	-----------	--------	----------	----------	------------------	--------------	----------------	-------



17	Irrigation - Coverage	Completed	ACCEPTABLE	100/100(100%)	Ensure proper sprinkler coverage throughout turf and planter areas.	Gustavo Martinez	1/30/2025 09:03 AM	NA
----	-----------------------	-----------	------------	---------------	---	------------------	--------------------	----

Notes: Coverage is correct.

After Image:

#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
---	-----------	--------	----------	----------	------------------	--------------	----------------	-------



#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
---	-----------	--------	----------	----------	------------------	--------------	----------------	-------



18	Irrigation - Wet spots	Completed	ACCEPTABLE	100/100(100%)	Inspect areas of service for wet spots in turf and planters. Adjust and repair irrigation as needed.	Gustavo Martinez	1/30/2025 09:08 AM	NA
----	------------------------	-----------	------------	---------------	--	------------------	--------------------	----

#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
19	Irrigation - Valve boxes	Completed	ACCEPTABLE	100/100(100%)	Inspect areas of service for broken or missing valve box lids.	Gustavo Martinez	1/30/2025 08:53 AM	NA

Notes: Valve boxes are in good shape.

After Image:



#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
---	-----------	--------	----------	----------	------------------	--------------	----------------	-------



#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
20	Trees - Down and broken branches	Completed	ACCEPTABLE	100/100(100%)	Removed down and broken branches.	Gustavo Martinez	1/30/2025 08:55 AM	NA

Notes: No trees/branches to report.

#	Task Name	Status	Response	Score(%)	Task Description	Inspected By	Inspected Date	Price
21	Trees - Sidewalks /Streets	Completed	ACCEPTABLE	100/100(100%)	Inspect areas of service to ensure trees are not encroaching on right of ways.	Gustavo Martinez	1/30/2025 08:55 AM	NA

